

 Sanctuary

Taylor Street Odor Control Systems  
and Report Log

System	Status	Notes
Loading Hi-Speed Door #2	Online	
Loading Hi-Speed Door #1	Online	
Air Curtain – Receiving Area	Online	
Hallway Carbon System #4	Online	
Carbon Exhaust System	Online	
Ozone Exhaust/Heat Relief Fan	Online	
Ozone Injection System	Online	
Receiving Dock Hi-Speed Door	Online	
Air Curtain #3 – Receiving /Hallway	Online	
Carbon System #3 – Receiving Dock	Online	
Water Treatment Hi-Speed Door	Online	
Air Curtain #2 – Water Treatment/Hall	Online	
Carbon System #2 – Process Hallway	Online	
Air Curtain – Office/Process Areas	Online	
Carbon System #1 – office area	Online	

Carbon System #1 – office  
area

Online

### Report Log

Date	Time	Location	Wind	Odor Level (See key)	Action Items/Remarks
31/01/2024	9:00 AM	Front Lot	N	1	N/A
17/01/2024	8:54 AM	Front Lot	NW	1	N/A

### Odor Level Key

1	Odor up to marginally detectable
2	Readily detectable to marginally recognizable
3	Readily recognizable
N/A	Upwind Location - N/A

Last Updated: 1-24-2024